

SWITCH036

AIRBASE INDUSTRIES PRESASURE SWITCH

Main screw- Clockwise increase BOTH cut in and cut out. MAXIMUM is 185 PSI (Recommended 175PSI). Counterclockwise decreases cut in and cut out. 1 full rotation is equivalent to roughly 10 PSI difference. Minimum cut out is 135 PSI

Differential Screw- Clockwise increases cut in pressure ONLY. Counterclockwise decreases cut in pressure minimum of 135 psi

IMPORTANT:

Wiring: wires must not cross sides and result will be damage to switch and possible shock hazard to operator. Lines must maintain vertically paired placement only.




Diagram for remote ON/OFF

Run the wires to the on off switch to these terminals marked motor.

Move the stock wires to the starter here to the terminals marked line

